

## Optional accessories

1

**GMK 38**

Art. no. 601261

**Connection cable**

(BNC to 2 x banana plug) approx. 90 cm long

2

**GHE 91**

Art. no. 601262

**Reciprocating piston electrode \***

to drive measuring nails into material without auxiliary devices

3

**GSE 91**

Art. no. 601266

**Impact electrode \***

to drive measuring nails into material

4

**GEG 91**

Art. no. 601268

**Handle**

suitable for GSE 91

5

**GSG 91**

Art. no. 601270

**Penetration electrode \***

adequate for steel nails and measuring rods

6

**GST 91**

Art. no. 601273

**steel nails**

9 steel nails (3 pieces each, 12, 16 and 23 mm long) in plastic case, Ø 2.5 mm

**GST 91/40**

Art. no. 601275

**steel nails**

10 steel nails, 40 mm long, Ø 2.5 mm, in plastic case

7

**GST 45i**

Art. no. 601277

**steel nails**

2 Teflon isolated steel nails, 45 mm long, Ø 2.5 mm

**GST 60i**

Art. no. 601279

**steel nails, as above, 60 mm long**

8

**GOK 91**

Art. no. 601287

**Measuring cap**

Surface measuring caps (pair) (for use with GSG 91 or GSE 91)

9


**GMS 300/91**

Art. no. 601289

**Measuring rods**

300 mm long (pair), for wood chips, wood wool, paper, carton, etc. (for use with GSG 91 or GSE 91)

10

**GST 15B**

Art. no. 601281

**steel nails \***

2 steel nails with bore hole, 15 mm long, Ø 3.8 mm (for direct connection of measuring cable GMK 38)

**GST 25B**

Art. no. 601283

**steel nails \* as above, Ø 3.8 x 25 mm****GST 40B**

Art. no. 601285

**steel nails \* as above, Ø 3.8 x 40 mm**

11

**GBSK 91**

Art. no. 601293

**Wire brush (pair) short \***

for depths up to approx. 100 mm

12

**GBSL 91**

Art. no. 601294

**Wire brush (pair) long \***

for depths up to approx. 300 mm

13

**GEF 38**

Art. no. 601296

**Flat electrode (pair) \***

for screed, paper, etc.

14

**GLP 91**

Art. no. 601299

**conducting paste**

100 ml, for surface measurements and depth indication in walls, wash floors etc. with brush probes

15

**GSP 91**

Art. no. 601301

**sensor for surface measurements \***

on paper, textiles etc.

**GSP 91 ES**

Art. no. 601303

**spare sensor element**

for GSP 91

16

**GMZ 38**

Art. no. 605783

**Measuring clamp \***

for measurements of veneers or thin wood (up to approx. 10 mm)

17

**GSF 50 (110 cm)**

Art. no. 601306

**GSF 50K (43 cm)**

Art. no. 601308

**Injection probe**

(without temperature sensor) for measurement up to a depth of 40 cm or 107 cm, incl. 1 m connection cable. Suitable for: wood chips, wood wool, straw, hay, grain, saw dust, etc.

18

**GSF 50TF (110 cm)**

Art. no. 601312

**GSF 50TFK (43 cm)**

Art. no. 601314

**Injection probe**

(with temperature sensor) for measurement up to a depth of 40 cm or 107 cm, incl. 1 m connection cable. Suitable for: wood chips, wood wool, straw, hay, grain, saw dust, etc.

\* Measuring cable GMK 38 necessary for GHE 91, GSE 91, GSG 91, GST 15B / 25B / 40B, GBSK 91, GBSL 91, GEF 38, GSP 91, GMZ 38